



Photo 1: View of the project area from the southeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the southeastern corner facing northward. Project area is largely snow covered at this time.



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of the western portion of the project area from the southwestern corner facing northward.