

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2017

Submitted Date:

03/13/2017

Document Number:

666803016

FIELD INSPECTION FORM

Loc ID 335064 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

15 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279727	WELL	PR	06/08/2006	GW	045-11080	CLOUGH RWF 33-15	PR
280090	WELL	PR	04/24/2007	GW	045-11177	CLOUGH RMV 140-15	PR
280091	WELL	PR	06/08/2006	GW	045-11178	CLOUGH RWF 343-15	PR
280093	WELL	PR	06/08/2006	GW	045-11179	CLOUGH RWF 443-15	PR
280094	WELL	PR	06/08/2006	GW	045-11180	CLOUGH RWF 43-15	PR
280098	WELL	PR	06/08/2006	GW	045-11183	CLOUGH RWF 444-15	PR
280099	WELL	PR	06/08/2006	GW	045-11184	CLOUGH RFW 344-15	PR
280100	WELL	PR	08/31/2007	GW	045-11185	CLOUGH RWF 543-15	PR
280101	WELL	PR	06/08/2006	GW	045-11186	CLOUGH RWF 434-15	PR
280102	WELL	PR	09/09/2007	GW	045-11187	CLOUGH RWF 334-15	PR
280103	WELL	PR	06/08/2006	GW	045-11188	CLOUGH RWF 333-15	PR
280104	WELL	PR	06/08/2006	GW	045-11189	CLOUGH RWF 433-15	PR
280106	WELL	PR	06/08/2006	GW	045-11190	CLOUGH RWF 533-15	PR

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Plunger Lift	# 13				
Type: Horizontal Heated Separator	# 14				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	200 BBLS	STEEL AST			

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:

Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		39.520512,-107.870493

Comment:

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	279727	Type:	WELL	API Number:	045-11080	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	280090	Type:	WELL	API Number:	045-11177	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	280091	Type:	WELL	API Number:	045-11178	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	280093	Type:	WELL	API Number:	045-11179	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	280094	Type:	WELL	API Number:	045-11180	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	280098	Type:	WELL	API Number:	045-11183	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	280099	Type:	WELL	API Number:	045-11184	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	280100	Type:	WELL	API Number:	045-11185	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 280101	Type: WELL	API Number: 045-11186	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 280102	Type: WELL	API Number: 045-11187	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 280103	Type: WELL	API Number: 045-11188	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 280104	Type: WELL	API Number: 045-11189	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	
Facility ID: 280106	Type: WELL	API Number: 045-11190	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Plunger lift			
Corrective Action:			Date:	

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): NO

Comment:

Pilot: Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Seeding	Pass					
Gravel	Pass					
		Gravel	Pass			
Retention Ponds	Pass					
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT