

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2017

Submitted Date:

03/13/2017

Document Number:

666803018**FIELD INSPECTION FORM**

Loc ID 335159 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name  | Phone | Email                              | Comment                           |
|---------------|-------|------------------------------------|-----------------------------------|
| , Inspections |       | COGCCInspectionReports@terraep.com | <a href="#">Field Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 288866      | WELL | PR     | 07/17/2007  | GW         | 045-13602 | CLOUGH RWF 324-14 | PR          |
| 288867      | WELL | PR     | 01/10/2007  | GW         | 045-13601 | CLOUGH RWF 24-14  | PR          |
| 288868      | WELL | PR     | 01/10/2007  | GW         | 045-13600 | CLOUGH RWF 14-14  | PR          |
| 288869      | WELL | PR     | 01/10/2007  | GW         | 045-13599 | CLOUGH RWF 314-14 | PR          |
| 288870      | WELL | PR     | 01/10/2007  | GW         | 045-13598 | CLOUGH RWF 414-14 | PR          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 5

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 5

Comment:

Corrective Action:

Date:

**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |       |
|--------------------|---|----------|-----------|---------|-----------------------|-------|
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | 39.520746,-107.865189 |       |
| Comment:           |   |          |           |         |                       |       |
| Corrective Action: |   |          |           |         |                       | Date: |

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     |             |
|                    |          |                     |                     |             |
| Date:              |          |                     |                     |             |

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

| Type |  |
|------|--|
|------|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities  |              |       |      |             |           |         |    |               |    |
|-----------------------|--------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:          | 288866       | Type: | WELL | API Number: | 045-13602 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288867       | Type: | WELL | API Number: | 045-13601 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288868       | Type: | WELL | API Number: | 045-13600 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288869       | Type: | WELL | API Number: | 045-13599 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |
| Facility ID:          | 288870       | Type: | WELL | API Number: | 045-13598 | Status: | PR | Insp. Status: | PR |
| <b>Producing Well</b> |              |       |      |             |           |         |    |               |    |
| Comment:              | Plunger lift |       |      |             |           |         |    |               |    |
| Corrective Action:    |              |       |      |             |           | Date:   |    |               |    |

## Environmental

### Spill/Remediation:

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Culverts                | Pass                  |               |                          |         |
|                  |                 | Gravel                  | Pass                  |               |                          |         |
| Ditches          | Pass            |                         |                       |               |                          |         |
| Berms            | Pass            |                         |                       |               |                          |         |
| Retention Ponds  | Pass            |                         |                       |               |                          |         |
|                  |                 | Ditches                 | Pass                  |               |                          |         |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT