

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2017

Submitted Date:

03/13/2017

Document Number:

666803020

### FIELD INSPECTION FORM

Loc ID 335572 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: PO BOX 370  
 City: PARACHUTE State: CO Zip: 81635

**Findings:**

20 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210467	WELL	PR	10/01/1993	GW	045-06223	MCNARY 106	PR
279725	WELL	PR	08/02/2006	GW	045-11082	CLOUGH RWF 341-15	PR
279985	WELL	PR	06/08/2006	GW	045-11129	CLOUGH RWF 332-15	PR
279987	WELL	PR	06/08/2006	GW	045-11130	CLOUGH RWF 432-15	PR
279988	WELL	PR	09/13/2005	GW	045-11131	CLOUGH RWF 431-15	PR
279991	WELL	PR	08/03/2006	GW	045-11132	CLOUGH RWF 531-15	PR
279993	WELL	PR	05/30/2006	GW	045-11133	CLOUGH RWF 541-15	PR
279994	WELL	PR	08/01/2006	GW	045-11134	CLOUGH RWF 41-15	PR
279995	WELL	PR	06/08/2006	GW	045-11135	CLOUGH RWF 32-15	PR
279998	WELL	PR	09/13/2005	GW	045-11136	CLOUGH RWF 542-15	PR
280000	WELL	PR	09/13/2005	GW	045-11137	CLOUGH RWF 31-15	PR
280002	WELL	PR	09/13/2005	GW	045-11138	CLOUGH RWF 331-15	PR
280004	WELL	PR	06/08/2006	GW	045-11139	CLOUGH RWF 42-15	PR
280005	WELL	PR	09/12/2006	GW	045-11140	CLOUGH RWF 342-15	PR
280006	WELL	PR	09/13/2005	GW	045-11141	CLOUGH RWF 442-15	PR
280018	WELL	PR	08/02/2006	GW	045-11153	CLOUGH RWF 441-15	PR
280019	WELL	PR	08/01/2014	GW	045-11154	CLOUGH RWF 532-15	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	corrective date
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 16	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 16	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:	Centralized battery				

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		39.529397,-107.871764
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	210467	Type:	WELL	API Number:	045-06223	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	279725	Type:	WELL	API Number:	045-11082	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279985	Type:	WELL	API Number:	045-11129	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279987	Type:	WELL	API Number:	045-11130	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279988	Type:	WELL	API Number:	045-11131	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279991	Type:	WELL	API Number:	045-11132	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279993	Type:	WELL	API Number:	045-11133	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279994	Type:	WELL	API Number:	045-11134	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID: 279995	Type: WELL	API Number: 045-11135	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 279998	Type: WELL	API Number: 045-11136	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 280000	Type: WELL	API Number: 045-11137	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 280002	Type: WELL	API Number: 045-11138	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 280004	Type: WELL	API Number: 045-11139	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 280005	Type: WELL	API Number: 045-11140	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 280006	Type: WELL	API Number: 045-11141	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:
Facility ID: 280018	Type: WELL	API Number: 045-11153	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Plunger lift				
Corrective Action:				Date:

Facility ID: 280019 Type: WELL API Number: 045-11154 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
Culverts	Pass					
Slope Roughening	Pass					
		Ditches	Pass			
		Retention Ponds	Pass			
		Gravel	Pass			
Ditches	Pass					
		Sediment Traps	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT