



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*) and smooth brome (*Bromus inermis*).



Photo 3: View of the western portion of the project area from the northwestern corner facing southward.



Photo 4: View of sediment over-topping wattles in the eastern portion of the project area.



Photo 5: View of erosional channel flowing beneath wattle in the eastern portion of the project area.



Photo 6: View of another area where stormwater flows beneath the wattles in the eastern portion of the project area.