

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/14/2017

Submitted Date:

03/14/2017

Document Number:

666803021**FIELD INSPECTION FORM**

Loc ID 335066	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: <u>20</u> Number of Comments <u>0</u> Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284277	WELL	PR	04/13/2006	GW	045-12122	SAVAGE RWF 231-32	PR
284279	WELL	PR	04/13/2006	GW	045-12123	SAVAGE RWF 341-32	PR
284281	WELL	PR	04/13/2006	GW	045-12125	SAVAGE RWF 232-32	PR
284282	WELL	PR	04/02/2007	GW	045-12126	SAVAGE RWF 242-32	PR
286745	WELL	PR	09/11/2014	GW	045-12758	SAVAGE RWF 441-32	PR
286747	WELL	PR	10/03/2014	GW	045-12757	SAVAGE RWF 332-32	PR
286748	WELL	PR	09/15/2006	GW	045-12756	SAVAGE RWF 32-32	PR
286749	WELL	PR	09/15/2006	GW	045-12755	SAVAGE RWF 331-32	PR
286750	WELL	PR	09/15/2006	GW	045-12754	SAVAGE RWF 31-32	PR
286751	WELL	PR	09/15/2006	GW	045-12753	SAVAGE RWF 541-32	PR
286752	WELL	PR	09/15/2006	GW	045-12752	SAVAGE RWF 442-32	PR
286753	WELL	PR	10/31/2007	GW	045-12751	SAVAGE RWF 42-32	PR
286754	WELL	PR	10/03/2014	GW	045-12750	SAVAGE RWF 342-32	PR
286755	WELL	PR	09/11/2014	GW	045-12749	SAVAGE RWF 41-32	PR
286756	WELL	PR	09/15/2006	GW	045-12748	SAVAGE RWF 241-32	PR
286784	WELL	PR	03/18/2008	GW	045-12773	SAVAGE RWF 431-32	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

16

Comment: Corrective Action: Date:

Type: Ancillary equipment

3

Comment: [Chemical unit at wellhead](#)Corrective Action: Date:

Type: Plunger Lift

16

Comment: Corrective Action: Date:

Type: Pig Station

1

Comment: Corrective Action: Date:

Type: Gas Meter Run

1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:	<input type="text"/>					Date: <input type="text"/>

Paint

Condition: Adequate

Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
METHANOL	1	OTHER	STEEL AST		,		
Comment:		At pig station					
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)		500gal					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate			
Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	300 BBLs	STEEL AST		39.485146,-107.908790		
Comment:							
Corrective Action:				Date:			
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Insufficient	Adequate			
Comment:							
Corrective Action:				Date:			
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:				Date:			
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:				Date:			

Inspected Facilities						
Facility ID:	284277	Type:	WELL	API Number: 045-12122	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	284279	Type:	WELL	API Number: 045-12123	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	284281	Type:	WELL	API Number: 045-12125	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	284282	Type:	WELL	API Number: 045-12126	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	286745	Type:	WELL	API Number: 045-12758	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	286747	Type:	WELL	API Number: 045-12757	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	286748	Type:	WELL	API Number: 045-12756	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	286749	Type:	WELL	API Number: 045-12755	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:

Facility ID:	286750	Type:	WELL	API Number:	045-12754	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286751	Type:	WELL	API Number:	045-12753	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286752	Type:	WELL	API Number:	045-12752	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286753	Type:	WELL	API Number:	045-12751	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286754	Type:	WELL	API Number:	045-12750	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286755	Type:	WELL	API Number:	045-12749	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286756	Type:	WELL	API Number:	045-12748	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	286784	Type:	WELL	API Number:	045-12773	Status:	PR	Insp. Status:	PR
<u>Producing Well</u>									
Comment:	Plunger lift								
Corrective Action:						Date:			

--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
		Culverts	Pass			
		Gravel	Pass			
Berms	Pass					
Compaction	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT