

Reference Area Photographs

Inspection Conducted on March 08,2017

SG Interests

Location ID #324469

Federal 11-90-24 #1 (Fed 24-1)

Spill Point ID #449436

SG Fed 24-1



Sign by the tank battery



Tank Battery (4 tanks) Earthen Berm

SG Fed 24-1



Secondary Containment. Hole at the center of the photo was excavated for soil sampling purposes.



Roadside ditch with snow melt. Rock check dams to control velocity, erosion and sediments. SG environmental consultant took soil samples near the tank battery, at a location down on the side ditch (bottom of photo), and halfway (up-gradient of where people are standing).