

2/22/2017 Photographs



Spill source area.



View northwest, north of the spill area.



View northeast, north of the spill area.



View east north of the spill area. Backfill stockpiles.



View east along the south shoulder of County Rd 74.



View east along the north shoulder of County Rd 74.



View north from north shoulder of County Rd 74 at impacted vegetation.




View north along the east edge of impacted vegetation north of County Rd 74.



View northeast.



View west.



Very thin accumulation of oil on exposed soil.



Variable accumulation of oil on exposed soil.