



**Photo 1:** View of the project area from the southeastern corner facing center.



**Photo 2:** View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*), intermediate wheatgrass (*Thinopyron intermedium*), and smooth brome (*Bromus inermis*).



**Photo 3: View of the western portion of the project area from the northwestern corner facing southward.**



**Photo 4: View of erosion occurring around cobble run-down in the eastern portion of the project area.**