

Inspection Photos
Location Name: Bethyl GW 29-12
API: 05-123-36782



Photo 1: TA wellhead, looking SW



Photo 2: Sediment discharge on E side of location, looking E