

Inspection Photos
Location Name: Ball Ranch GW 27-63HN
API: 05-123-35058



Photo 1: Unlabeled vault



Photo 2: Stained soil at exhaust