

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/15/2017

Submitted Date:

03/16/2017

Document Number:

675204021**FIELD INSPECTION FORM**Loc ID 414077 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone          | Email                        | Comment                            |
|-----------------|----------------|------------------------------|------------------------------------|
| Hartman, Robert | (970) 244-3041 | bhartman@blm.gov             | <a href="#">Petroleum Engineer</a> |
| Encana,         |                | cogcc.inspections@encana.com | <a href="#">All Inspections</a>    |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                   | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------------|-------------|
| 412710      | WELL | PR     | 08/08/2011  | GW         | 045-18535 | Daybreak Federal 30-11BB (PL30) | PR          |
| 412711      | WELL | PR     | 07/12/2011  | GW         | 045-18536 | Daybreak Federal 25-9BB (PL30)  | PR          |
| 412712      | WELL | PR     | 10/10/2011  | GW         | 045-18537 | Daybreak Federal 30-12BB (PL30) | PR          |
| 412713      | WELL | PR     | 07/08/2011  | GW         | 045-18538 | Daybreak Federal 30-13BB (PL30) | PR          |
| 412714      | WELL | PR     | 10/14/2011  | GW         | 045-18539 | Daybreak Federal 30-12 (PL30)   | PR          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |  |
|----------------|------|--------|--|--|
| <b>Spills:</b> |      |        |  |  |
| Type           | Area | Volume |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 500 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CONDENSATE         | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|           |          |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

|                  |  |
|------------------|--|
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities       |                   |                              |                   |                         |
|----------------------------|-------------------|------------------------------|-------------------|-------------------------|
| Facility ID: <u>412710</u> | Type: <u>WELL</u> | API Number: <u>045-18535</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>412711</u> | Type: <u>WELL</u> | API Number: <u>045-18536</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>412712</u> | Type: <u>WELL</u> | API Number: <u>045-18537</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>412713</u> | Type: <u>WELL</u> | API Number: <u>045-18538</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |
| Facility ID: <u>412714</u> | Type: <u>WELL</u> | API Number: <u>045-18539</u> | Status: <u>PR</u> | Insp. Status: <u>PR</u> |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction       | Pass            | Gravel                  | Pass                  |               |                          |         |
| Berms            | Pass            | Compaction              | Pass                  |               |                          |         |
| Gravel           | Pass            |                         |                       |               |                          |         |
| Retention Ponds  | Pass            |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 675204022    | PL 30 Pad   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099423">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4099423</a> |