

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/06/2017

Submitted Date:

03/15/2017

Document Number:

680301758

FIELD INSPECTION FORM

Loc ID 304782 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 75027
Name of Operator: ROSEWOOD RESOURCES INC
Address: 2101 CEDAR SPRINGS RD STE 1500
City: DALLAS State: TX Zip: 75201

Findings:

- 9 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Krehmeyer, James	970-848-2228	jkrehmeyer@rosewd.com	Cell # 970-630-3880

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
274917	WELL	PR	04/12/2005	GW	125-08980	MCCONNELL 4-6	PR

General Comment:

[FIR Routine Site Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Locatied within irrigated cropland - seasonal access		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Satisfactory - Called Emergency Contact No. received live attendant.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 0		
Comment:	Flowing GW		
Corrective Action:			Date:

Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:			
Type			

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 274917 Type: WELL API Number: 125-08980 Status: PR Insp. Status: PR

Producing Well

Comment: [Flowing GW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT