

Photo#1:

BMPs have been installed around Northern Perimeter of Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gunderson
Loc#449070 #2

Photo#2:

Wattles area of Concern. Sediment has overwhelmed Wattles and now SW has cut out of ditch and Water is undercutting to where?



Photo#3:



March 12,2017

Photo#4:

Access Road in general is not stabilized.



Photo#5:

Loose soil is a Potential Pollution Source.



March 12,2017

Photo#6:

Arrows indicate where Soil begins to fill in ditch.



Photo#7:



March 12,2017

Photo#8:

View of Previous slide from opposite Direction.



March 12,2017

Photo#9:

Loose soil is a Potential Pollution Source.



Photo#10:

Access Road in general is not stabilized.



March 12,2017

Photo#11:



Photo#12:

Access Road in general is not stabilized.

Photo#13:



March 12, 2017