



Photo 1: View of the project area from the northeastern corner facing center.



Photo 2: View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is comprised of western wheatgrass (*Pascopyrum smithii*), crested wheatgrass (*Agropyron cristatum*), and smooth brome (*Bromus inermis*).



Photo 3: View of the northern portion of the project area from the northeastern corner facing center.



Photo 4: View of cobble stormwater run-down in the northeastern portion of the project area. Appears to be functioning at this time.



Photo 5: View of the western portion of the project area facing southward. Cobble run-down appears to be functioning at this time.