

Inspection Photos
Location Name: Ball Ranch AC15-04
API: 05-123-34890



Photo 1: Stained soil at crude oil tank



Photo 2: Stained soil at produced water vault