

Photo#1:
Overview of Location to SW.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Hawxhurst Loc#419498

Photo#2:

View of East end of Cut slope area. Insert is close up of Material at this end



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Hawxhurst Loc#419498

Photo#3:

View of West end of Cut slope area.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Hawxhurst Loc#419498