


Photo#1:  
View from NE Corner to SW.



Photo#2:  
View from SW Corner to NE  
Sound Walls going Up



March 15, 2017




**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: URSA BMC D Pad Loc#446582

Photo#3:

View of Newly Installed BMPs at South end of Site

Photo#4:



March 15, 2017



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: URSA BMC D Pad Loc#446582