

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/13/2017

Submitted Date:

03/13/2017

Document Number:

666803020**FIELD INSPECTION FORM**

Loc ID 335572	Inspector Name: Murray, Richard	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 20 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																																															
<b>Operator Information:</b> OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>																																																																																																																																																			
<b>Contact Information:</b> <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, Inspections</td> <td></td> <td>COGCCInspectionReports@terraep.com</td> <td><a href="#">Field Inspections</a></td> </tr> </table>					Contact Name	Phone	Email	Comment	, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>																																																																																																																																							
Contact Name	Phone	Email	Comment																																																																																																																																																
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>																																																																																																																																																
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>210467</td><td>WELL</td><td>PR</td><td>10/01/1993</td><td>GW</td><td>045-06223</td><td>MCNARY 106</td><td>PR</td></tr> <tr><td>279725</td><td>WELL</td><td>PR</td><td>08/02/2006</td><td>GW</td><td>045-11082</td><td>CLOUGH RWF 341-15</td><td>PR</td></tr> <tr><td>279985</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11129</td><td>CLOUGH RWF 332-15</td><td>PR</td></tr> <tr><td>279987</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11130</td><td>CLOUGH RWF 432-15</td><td>PR</td></tr> <tr><td>279988</td><td>WELL</td><td>PR</td><td>09/13/2005</td><td>GW</td><td>045-11131</td><td>CLOUGH RWF 431-15</td><td>PR</td></tr> <tr><td>279991</td><td>WELL</td><td>PR</td><td>08/03/2006</td><td>GW</td><td>045-11132</td><td>CLOUGH RWF 531-15</td><td>PR</td></tr> <tr><td>279993</td><td>WELL</td><td>PR</td><td>05/30/2006</td><td>GW</td><td>045-11133</td><td>CLOUGH RWF 541-15</td><td>PR</td></tr> <tr><td>279994</td><td>WELL</td><td>PR</td><td>08/01/2006</td><td>GW</td><td>045-11134</td><td>CLOUGH RWF 41-15</td><td>PR</td></tr> <tr><td>279995</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11135</td><td>CLOUGH RWF 32-15</td><td>PR</td></tr> <tr><td>279998</td><td>WELL</td><td>PR</td><td>09/13/2005</td><td>GW</td><td>045-11136</td><td>CLOUGH RWF 542-15</td><td>PR</td></tr> <tr><td>280000</td><td>WELL</td><td>PR</td><td>09/13/2005</td><td>GW</td><td>045-11137</td><td>CLOUGH RWF 31-15</td><td>PR</td></tr> <tr><td>280002</td><td>WELL</td><td>PR</td><td>09/13/2005</td><td>GW</td><td>045-11138</td><td>CLOUGH RWF 331-15</td><td>PR</td></tr> <tr><td>280004</td><td>WELL</td><td>PR</td><td>06/08/2006</td><td>GW</td><td>045-11139</td><td>CLOUGH RWF 42-15</td><td>PR</td></tr> <tr><td>280005</td><td>WELL</td><td>PR</td><td>09/12/2006</td><td>GW</td><td>045-11140</td><td>CLOUGH RWF 342-15</td><td>PR</td></tr> <tr><td>280006</td><td>WELL</td><td>PR</td><td>09/13/2005</td><td>GW</td><td>045-11141</td><td>CLOUGH RWF 442-15</td><td>PR</td></tr> <tr><td>280018</td><td>WELL</td><td>PR</td><td>08/02/2006</td><td>GW</td><td>045-11153</td><td>CLOUGH RWF 441-15</td><td>PR</td></tr> <tr><td>280019</td><td>WELL</td><td>PR</td><td>08/01/2014</td><td>GW</td><td>045-11154</td><td>CLOUGH RWF 532-15</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	210467	WELL	PR	10/01/1993	GW	045-06223	MCNARY 106	PR	279725	WELL	PR	08/02/2006	GW	045-11082	CLOUGH RWF 341-15	PR	279985	WELL	PR	06/08/2006	GW	045-11129	CLOUGH RWF 332-15	PR	279987	WELL	PR	06/08/2006	GW	045-11130	CLOUGH RWF 432-15	PR	279988	WELL	PR	09/13/2005	GW	045-11131	CLOUGH RWF 431-15	PR	279991	WELL	PR	08/03/2006	GW	045-11132	CLOUGH RWF 531-15	PR	279993	WELL	PR	05/30/2006	GW	045-11133	CLOUGH RWF 541-15	PR	279994	WELL	PR	08/01/2006	GW	045-11134	CLOUGH RWF 41-15	PR	279995	WELL	PR	06/08/2006	GW	045-11135	CLOUGH RWF 32-15	PR	279998	WELL	PR	09/13/2005	GW	045-11136	CLOUGH RWF 542-15	PR	280000	WELL	PR	09/13/2005	GW	045-11137	CLOUGH RWF 31-15	PR	280002	WELL	PR	09/13/2005	GW	045-11138	CLOUGH RWF 331-15	PR	280004	WELL	PR	06/08/2006	GW	045-11139	CLOUGH RWF 42-15	PR	280005	WELL	PR	09/12/2006	GW	045-11140	CLOUGH RWF 342-15	PR	280006	WELL	PR	09/13/2005	GW	045-11141	CLOUGH RWF 442-15	PR	280018	WELL	PR	08/02/2006	GW	045-11153	CLOUGH RWF 441-15	PR	280019	WELL	PR	08/01/2014	GW	045-11154	CLOUGH RWF 532-15	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																												
210467	WELL	PR	10/01/1993	GW	045-06223	MCNARY 106	PR																																																																																																																																												
279725	WELL	PR	08/02/2006	GW	045-11082	CLOUGH RWF 341-15	PR																																																																																																																																												
279985	WELL	PR	06/08/2006	GW	045-11129	CLOUGH RWF 332-15	PR																																																																																																																																												
279987	WELL	PR	06/08/2006	GW	045-11130	CLOUGH RWF 432-15	PR																																																																																																																																												
279988	WELL	PR	09/13/2005	GW	045-11131	CLOUGH RWF 431-15	PR																																																																																																																																												
279991	WELL	PR	08/03/2006	GW	045-11132	CLOUGH RWF 531-15	PR																																																																																																																																												
279993	WELL	PR	05/30/2006	GW	045-11133	CLOUGH RWF 541-15	PR																																																																																																																																												
279994	WELL	PR	08/01/2006	GW	045-11134	CLOUGH RWF 41-15	PR																																																																																																																																												
279995	WELL	PR	06/08/2006	GW	045-11135	CLOUGH RWF 32-15	PR																																																																																																																																												
279998	WELL	PR	09/13/2005	GW	045-11136	CLOUGH RWF 542-15	PR																																																																																																																																												
280000	WELL	PR	09/13/2005	GW	045-11137	CLOUGH RWF 31-15	PR																																																																																																																																												
280002	WELL	PR	09/13/2005	GW	045-11138	CLOUGH RWF 331-15	PR																																																																																																																																												
280004	WELL	PR	06/08/2006	GW	045-11139	CLOUGH RWF 42-15	PR																																																																																																																																												
280005	WELL	PR	09/12/2006	GW	045-11140	CLOUGH RWF 342-15	PR																																																																																																																																												
280006	WELL	PR	09/13/2005	GW	045-11141	CLOUGH RWF 442-15	PR																																																																																																																																												
280018	WELL	PR	08/02/2006	GW	045-11153	CLOUGH RWF 441-15	PR																																																																																																																																												
280019	WELL	PR	08/01/2014	GW	045-11154	CLOUGH RWF 532-15	PR																																																																																																																																												

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	<a href="#">Field Inspections</a>

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210467	WELL	PR	10/01/1993	GW	045-06223	MCNARY 106	PR
279725	WELL	PR	08/02/2006	GW	045-11082	CLOUGH RWF 341-15	PR
279985	WELL	PR	06/08/2006	GW	045-11129	CLOUGH RWF 332-15	PR
279987	WELL	PR	06/08/2006	GW	045-11130	CLOUGH RWF 432-15	PR
279988	WELL	PR	09/13/2005	GW	045-11131	CLOUGH RWF 431-15	PR
279991	WELL	PR	08/03/2006	GW	045-11132	CLOUGH RWF 531-15	PR
279993	WELL	PR	05/30/2006	GW	045-11133	CLOUGH RWF 541-15	PR
279994	WELL	PR	08/01/2006	GW	045-11134	CLOUGH RWF 41-15	PR
279995	WELL	PR	06/08/2006	GW	045-11135	CLOUGH RWF 32-15	PR
279998	WELL	PR	09/13/2005	GW	045-11136	CLOUGH RWF 542-15	PR
280000	WELL	PR	09/13/2005	GW	045-11137	CLOUGH RWF 31-15	PR
280002	WELL	PR	09/13/2005	GW	045-11138	CLOUGH RWF 331-15	PR
280004	WELL	PR	06/08/2006	GW	045-11139	CLOUGH RWF 42-15	PR
280005	WELL	PR	09/12/2006	GW	045-11140	CLOUGH RWF 342-15	PR
280006	WELL	PR	09/13/2005	GW	045-11141	CLOUGH RWF 442-15	PR
280018	WELL	PR	08/02/2006	GW	045-11153	CLOUGH RWF 441-15	PR
280019	WELL	PR	08/01/2014	GW	045-11154	CLOUGH RWF 532-15	PR

<b>General Comment:</b>
-------------------------

**Location**Overall Good: ☒

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Horizontal Heated Separator

# 16

Comment: Corrective Action: Date: 

Type: Plunger Lift

# 16

Comment: Corrective Action: Date: 

Type: Gas Meter Run

# 1

Comment: Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLS	STEEL AST		39.529397,-107.871764
Comment:	<input type="text"/>				
Corrective Action:	<input type="text"/>				Date: <input type="text"/>

**Paint**Condition Adequate Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Earth	Adequate		Walls Sufficent		Base Sufficient		Adequate			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID		SE GPS		
PRODUCED WATER		1	300 BBLS	STEEL AST				,		
Comment:		Centralized battery								

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	210467	Type:	WELL	API Number:	045-06223	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	279725	Type:	WELL	API Number:	045-11082	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279985	Type:	WELL	API Number:	045-11129	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279987	Type:	WELL	API Number:	045-11130	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279988	Type:	WELL	API Number:	045-11131	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279991	Type:	WELL	API Number:	045-11132	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279993	Type:	WELL	API Number:	045-11133	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	279994	Type:	WELL	API Number:	045-11134	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

Facility ID:	279995	Type:	WELL	API Number:	045-11135	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	279998	Type:	WELL	API Number:	045-11136	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	280000	Type:	WELL	API Number:	045-11137	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	280002	Type:	WELL	API Number:	045-11138	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	280004	Type:	WELL	API Number:	045-11139	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	280005	Type:	WELL	API Number:	045-11140	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	280006	Type:	WELL	API Number:	045-11141	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			
Facility ID:	280018	Type:	WELL	API Number:	045-11153	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Plunger lift								
Corrective Action:						Date:			

Facility ID:	280019	Type:	WELL	API Number:	045-11154	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well			
Comment:	Plunger lift		
Corrective Action:		Date:	

**Environmental**

**Spill/Remediation:**

Comment:

Corrective  
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps	Pass					
Culverts	Pass					
Slope Roughening	Pass					
		Sediment Traps	Pass			
Ditches	Pass					
		Gravel	Pass			
		Retention Ponds	Pass			
		Ditches	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401232479	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4097229">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4097229</a>