

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2017

Submitted Date:

03/20/2017

Document Number:

675204038

FIELD INSPECTION FORM

Loc ID 334084 Inspector Name: CONKLIN, CURTIS On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 100185

Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

Contact Information:

Contact Name	Phone	Email	Comment
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Encana,		cogcc.inspections@encana.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270393	WELL	PR	12/12/2003	GW	045-09547	ST. PARACHUTE TBI 36-32	PR
270395	WELL	PR	03/13/2004	GW	045-09548	S.PARACHUTE TBI 36-33D	PR
275593	WELL	PR	09/21/2010	GW	045-10354	TBI FEDERAL 36-13 PK36-7-96	PR
275596	WELL	PR	11/05/2005	GW	045-10357	TBI FEDERAL 36-15 (PK-36-7-	PR
275600	WELL	PR	03/01/2013	GW	045-10361	TBI FEDERAL 36-14 (PK-36-7-	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 270393 Type: WELL API Number: 045-09547 Status: PR Insp. Status: PR

Facility ID: 270395 Type: WELL API Number: 045-09548 Status: PR Insp. Status: PR

Facility ID: 275593 Type: WELL API Number: 045-10354 Status: PR Insp. Status: PR

Facility ID: 275596 Type: WELL API Number: 045-10357 Status: PR Insp. Status: PR

Facility ID: 275600 Type: WELL API Number: 045-10361 Status: PR Insp. Status: PR

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Gravel	Pass					
Compaction	Pass	Gravel	Pass			
Waddles	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT