



Photo 1: View of the project area from the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward.



Photo 3: View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4: View of the western portion of the project area from the southwestern corner facing northward.



Photo 5: View of wood debris and parked van in the western portion of the project area.



Photo 6: View of cement a fencing debris stored in the northern portion of the project area.