

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2017

Submitted Date:

03/08/2017

Document Number:

672500458**FIELD INSPECTION FORM**
 Loc ID 332974 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286924	WELL	PR	05/24/2012	OW	123-27305	DUKE USX J 5-9	PR
286925	WELL	PR	10/28/2008	OW	123-27304	Duke USX J 05-16	PR
286926	WELL	PR	03/28/2007	OW	123-27303	DUKE J 4-33	PR
286955	WELL	PR	07/19/2012	OW	123-27328	DUKE J 4-14	PR
286956	WELL	PR	08/26/2012	OW	123-27327	DUKE J 4-11	PR
286957	WELL	PR	06/28/2012	OW	123-27326	DUKE J 4-25	PR
286958	WELL	PR	04/09/2007	GW	123-27325	DUKE J 4-12	PR
286959	WELL	PR	05/31/2012	OW	123-27324	DUKE J 4-13	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	CHAIN LINK		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	6' CHAIN LINK		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	6' CHAIN LINK		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	METHANOL PUMP W/TANK		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLS	CONCRETE SUMP/VAULT		40.425850,-104.791990	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	300 BBLS	STEEL AST		40.425850,-104.791990	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: 286924	Type: WELL	API Number: 123-27305	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:		Date:		
BradenHead				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 286925	Type: WELL	API Number: 123-27304	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:		Date:		
BradenHead				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 286926	Type: WELL	API Number: 123-27303	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:		Date:		
BradenHead				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 286955	Type: WELL	API Number: 123-27328	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:		Date:		
BradenHead				
Comment: PLUMBED TO SURFACE				
Corrective Action:		Date:		
Facility ID: 286956	Type: WELL	API Number: 123-27327	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:		Date:		

BradenHead			
Comment: <u>PLUMBED TO SURFACE</u>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>286957</u>	Type: <u>WELL</u>	API Number: <u>123-27326</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>		Date: _____	
Corrective Action: _____		Date: _____	
BradenHead			
Comment: <u>PLUMBED TO SURFACE</u>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>286958</u>	Type: <u>WELL</u>	API Number: <u>123-27325</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>		Date: _____	
Corrective Action: _____		Date: _____	
BradenHead			
Comment: <u>PLUMBED TO SURFACE</u>		Date: _____	
Corrective Action: _____		Date: _____	
Facility ID: <u>286959</u>	Type: <u>WELL</u>	API Number: <u>123-27324</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Producing Well			
Comment: <u>PR</u>		Date: _____	
Corrective Action: _____		Date: _____	
BradenHead			
Comment: <u>PLUMBED TO SURFACE</u>		Date: _____	
Corrective Action: _____		Date: _____	

Environmental**Spills/Releases:**

Type of Spill:	_____	Estimated Spill Volume:	_____
Comment:	_____		
Corrective Action:	_____		Date: _____
Reportable:	_____	GPS: Lat _____	Long _____
Proximity to Surface Water:	_____	Depth to Ground Water:	_____

Water Well Complaint:

		Lat	Long
DWR Receipt Num:	_____	Owner Name:	_____
		GPS :	_____

Field Parameters:

Sample Location:	_____	Comment:	_____
------------------	-------	----------	-------

Spill/Remediation:

Comment:	_____		
Corrective Action:	_____	Date:	_____

Emission Control Burner (ECB): YES _____

Comment: _____

Pilot: ON _____ Wildlife Protection Devices (fired vessels): YES _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced Pass Recontoured Pass 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401232868	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4097808