

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/20/2017

Submitted Date:

03/21/2017

Document Number:

666803037

### FIELD INSPECTION FORM

Loc ID 335108 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282178	WELL	PR	12/22/2005	GW	045-11694	CLOUGH RWF 311-22	PR
282179	WELL	PR	09/14/2006	GW	045-11693	CLOUGH RWF 421-22	PR
282180	WELL	PR	02/13/2007	GW	045-11692	CLOUGH RWF 321-22	PR
282181	WELL	PR	09/15/2006	GW	045-11691	CLOUGH RWF 411-22	PR
282253	WELL	PR	12/28/2005	GW	045-11709	CLOUGH RWF 521-22	PR
282254	WELL	PR	12/28/2005	GW	045-11708	CLOUGH RWF 511-22	PR
282265	WELL	PR	09/15/2006	GW	045-11698	CLOUGH RWF 412-22	PR
282267	WELL	PR	10/10/2006	GW	045-11697	CLOUGH RWF 312-22	PR

**General Comment:**

Shared facilities with location ID 335215 and 324187

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#				corrective date
Horizontal Heated Separator	# 10				
Plunger Lift	# 8				
Gas Meter Run	# 1				

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	0				,	

**Paint**

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	200 BBLs	STEEL AST		,

Comment: [Centralized battery](#)

Corrective Action:	Date:
--------------------	-------

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		39.516652,-107.879530
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	282178	Type:	WELL	API Number:	045-11694	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	282179	Type:	WELL	API Number:	045-11693	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	282180	Type:	WELL	API Number:	045-11692	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	282181	Type:	WELL	API Number:	045-11691	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	282253	Type:	WELL	API Number:	045-11709	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	282254	Type:	WELL	API Number:	045-11708	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	282265	Type:	WELL	API Number:	045-11698	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				
Facility ID:	282267	Type:	WELL	API Number:	045-11697	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Plunger lift								
Corrective Action:					Date:				

--

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Retention Ponds	Pass			
Gravel	Pass					
		Culverts	Pass			
		Ditches	Pass			
		Rip Rap	Pass			
		Gravel	Pass			
Seeding	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT