



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the northern portion of the project area from the northwestern corner facing eastward. Revegetation is largely comprised of grasses such as crested wheatgrass (*Agropyron cristatum*) and Intermediate wheatgrass (*Thinopyron intermedium*), and smooth brome (*Bromus inermis*).



Photo 3: View of the eastern portion of the project area from the southeastern corner facing northeastward.



Photo 4: View of the western portion of the project area from the northwestern corner facing southward.



Photo 5: View of stormwater controls in the northwestern portion of the project area appear to be functioning.



Photo 6: View of functioning sign next to a sign that is no longer functioning and should be removed.