

Photo#1:
Overview of Location to West



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Ware Loc#449385

Photo#2:

View of Access Road Work to East.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Ware Loc#449385

Photo#3:

Construction was just commencing. Contractor indicated that Roughening or Appropriate BMP would be installed by Day end at juncture of Access Road entrance with Local Scribbner Lane Rd.



Photo#4:



March 20,2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Ware Loc#449385

Photo#5:

Contractor Indicated that exploratory Pipe line bore holes at juncture of Access Road entrance with Local Rd would be covered to prevent Endangerment of Wildlife by end of Day. Refer to Photos attached..



March 20,2017

Photo#6:

