


Photo#1:

Aerial Views of Location, showing that Pad size has not been Reduced. Circles indicate areas of Volunteer Vegetation.



March 12, 2017

Photo#2:

South end of Location with Volunteer Vegetation in Graveled area.



March 12, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Laramie Gipp Loc#334501