

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2017

Submitted Date:

03/21/2017

Document Number:

680101591**FIELD INSPECTION FORM**

Loc ID 449385	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 7 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested																																																																																																																																																																																																							
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>PO BOX 370</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>																																																																																																																																																																																																											
Contact Information: <table border="1"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td></td> <td></td> <td>COGCCInspectionReports@terraep.com</td> <td>All Inspections</td> </tr> </table>					Contact Name	Phone	Email	Comment			COGCCInspectionReports@terraep.com	All Inspections																																																																																																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																																																																																																								
		COGCCInspectionReports@terraep.com	All Inspections																																																																																																																																																																																																								
Inspected Facilities: <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>449386</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23434</td><td>WARE SR 533-12</td><td>CI</td></tr> <tr><td>449387</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23435</td><td>WARE SR 514-12</td><td>CI</td></tr> <tr><td>449388</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23436</td><td>WARE SR 14-12</td><td>CI</td></tr> <tr><td>449389</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23437</td><td>WARE SR 324-12</td><td>CI</td></tr> <tr><td>449390</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23438</td><td>WARE SR 34-12</td><td>CI</td></tr> <tr><td>449391</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23439</td><td>WARE SR 23-12</td><td>CI</td></tr> <tr><td>449392</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23440</td><td>WARE SR 423-12</td><td>CI</td></tr> <tr><td>449393</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23441</td><td>WARE SR 513-12</td><td>CI</td></tr> <tr><td>449394</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23442</td><td>WARE SR 523-12</td><td>CI</td></tr> <tr><td>449395</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23443</td><td>WARE SR 413-12</td><td>CI</td></tr> <tr><td>449396</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23444</td><td>WARE SR 512-12</td><td>CI</td></tr> <tr><td>449397</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23445</td><td>WARE SR 24-12</td><td>CI</td></tr> <tr><td>449398</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23446</td><td>WARE SR 524-12</td><td>CI</td></tr> <tr><td>449399</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23447</td><td>WARE SR 522-12</td><td>CI</td></tr> <tr><td>449400</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23448</td><td>WARE SR 313-12</td><td>CI</td></tr> <tr><td>449401</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23449</td><td>WARE SR 412-12</td><td>CI</td></tr> <tr><td>449402</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23450</td><td>WARE SR 424-12</td><td>CI</td></tr> <tr><td>449403</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23451</td><td>WARE SR 334-12</td><td>CI</td></tr> <tr><td>449404</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23452</td><td>WARE SR 323-12</td><td>CI</td></tr> <tr><td>449405</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23453</td><td>WARE SR 314-12</td><td>CI</td></tr> <tr><td>449406</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23454</td><td>WARE SR 13-12</td><td>CI</td></tr> <tr><td>449407</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23455</td><td>WARE SR 414-12</td><td>CI</td></tr> <tr><td>449408</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23456</td><td>WARE SR 433-12</td><td>CI</td></tr> <tr><td>449409</td><td>WELL</td><td>XX</td><td>02/28/2017</td><td></td><td>045-23457</td><td>WARE SR 534-12</td><td>CI</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	449386	WELL	XX	02/28/2017		045-23434	WARE SR 533-12	CI	449387	WELL	XX	02/28/2017		045-23435	WARE SR 514-12	CI	449388	WELL	XX	02/28/2017		045-23436	WARE SR 14-12	CI	449389	WELL	XX	02/28/2017		045-23437	WARE SR 324-12	CI	449390	WELL	XX	02/28/2017		045-23438	WARE SR 34-12	CI	449391	WELL	XX	02/28/2017		045-23439	WARE SR 23-12	CI	449392	WELL	XX	02/28/2017		045-23440	WARE SR 423-12	CI	449393	WELL	XX	02/28/2017		045-23441	WARE SR 513-12	CI	449394	WELL	XX	02/28/2017		045-23442	WARE SR 523-12	CI	449395	WELL	XX	02/28/2017		045-23443	WARE SR 413-12	CI	449396	WELL	XX	02/28/2017		045-23444	WARE SR 512-12	CI	449397	WELL	XX	02/28/2017		045-23445	WARE SR 24-12	CI	449398	WELL	XX	02/28/2017		045-23446	WARE SR 524-12	CI	449399	WELL	XX	02/28/2017		045-23447	WARE SR 522-12	CI	449400	WELL	XX	02/28/2017		045-23448	WARE SR 313-12	CI	449401	WELL	XX	02/28/2017		045-23449	WARE SR 412-12	CI	449402	WELL	XX	02/28/2017		045-23450	WARE SR 424-12	CI	449403	WELL	XX	02/28/2017		045-23451	WARE SR 334-12	CI	449404	WELL	XX	02/28/2017		045-23452	WARE SR 323-12	CI	449405	WELL	XX	02/28/2017		045-23453	WARE SR 314-12	CI	449406	WELL	XX	02/28/2017		045-23454	WARE SR 13-12	CI	449407	WELL	XX	02/28/2017		045-23455	WARE SR 414-12	CI	449408	WELL	XX	02/28/2017		045-23456	WARE SR 433-12	CI	449409	WELL	XX	02/28/2017		045-23457	WARE SR 534-12	CI
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																																																																																				
449386	WELL	XX	02/28/2017		045-23434	WARE SR 533-12	CI																																																																																																																																																																																																				
449387	WELL	XX	02/28/2017		045-23435	WARE SR 514-12	CI																																																																																																																																																																																																				
449388	WELL	XX	02/28/2017		045-23436	WARE SR 14-12	CI																																																																																																																																																																																																				
449389	WELL	XX	02/28/2017		045-23437	WARE SR 324-12	CI																																																																																																																																																																																																				
449390	WELL	XX	02/28/2017		045-23438	WARE SR 34-12	CI																																																																																																																																																																																																				
449391	WELL	XX	02/28/2017		045-23439	WARE SR 23-12	CI																																																																																																																																																																																																				
449392	WELL	XX	02/28/2017		045-23440	WARE SR 423-12	CI																																																																																																																																																																																																				
449393	WELL	XX	02/28/2017		045-23441	WARE SR 513-12	CI																																																																																																																																																																																																				
449394	WELL	XX	02/28/2017		045-23442	WARE SR 523-12	CI																																																																																																																																																																																																				
449395	WELL	XX	02/28/2017		045-23443	WARE SR 413-12	CI																																																																																																																																																																																																				
449396	WELL	XX	02/28/2017		045-23444	WARE SR 512-12	CI																																																																																																																																																																																																				
449397	WELL	XX	02/28/2017		045-23445	WARE SR 24-12	CI																																																																																																																																																																																																				
449398	WELL	XX	02/28/2017		045-23446	WARE SR 524-12	CI																																																																																																																																																																																																				
449399	WELL	XX	02/28/2017		045-23447	WARE SR 522-12	CI																																																																																																																																																																																																				
449400	WELL	XX	02/28/2017		045-23448	WARE SR 313-12	CI																																																																																																																																																																																																				
449401	WELL	XX	02/28/2017		045-23449	WARE SR 412-12	CI																																																																																																																																																																																																				
449402	WELL	XX	02/28/2017		045-23450	WARE SR 424-12	CI																																																																																																																																																																																																				
449403	WELL	XX	02/28/2017		045-23451	WARE SR 334-12	CI																																																																																																																																																																																																				
449404	WELL	XX	02/28/2017		045-23452	WARE SR 323-12	CI																																																																																																																																																																																																				
449405	WELL	XX	02/28/2017		045-23453	WARE SR 314-12	CI																																																																																																																																																																																																				
449406	WELL	XX	02/28/2017		045-23454	WARE SR 13-12	CI																																																																																																																																																																																																				
449407	WELL	XX	02/28/2017		045-23455	WARE SR 414-12	CI																																																																																																																																																																																																				
449408	WELL	XX	02/28/2017		045-23456	WARE SR 433-12	CI																																																																																																																																																																																																				
449409	WELL	XX	02/28/2017		045-23457	WARE SR 534-12	CI																																																																																																																																																																																																				

General Comment:

This is a Construction and Stormwater Inspection. Form 42 (Notice of Construction) has been Filed for this Location; Start Date as /13/2017. .Conditions at time of Inspection were Overcast, Hazy at 68 degrees.

Location Construction

Location ID: 449385 CDP: _____

Comment: Pipe line work had commenced on 3/13/17, line from Lower Youberg Loc to new Location Installed. Site has had Bush clipped/beat. Construction on Access road was in Progress with two Link Belts Operating at time of Inspection.

Corrective Action: _____ Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____ Date: _____

Wildlife BMPs:

Comment: This location is included in a Wildlife Mitigation Plan. The facility lies within the external buffer zone of the Beaver Creek 317B area. Therefore by COGCC rule, the 317B buffer zone classifies the facility as being in a sensitive area.

Corrective Action: _____ Date: _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present
SLOPE ROUGHENING	No		

Comments: Erosion BMPs: Construction was just commencing. Contractor indicated that Roughening or Appropriate BMP would be installed by Day end at juncture of Access Road entrance with Local Scribner Lane Rd.

Other BMPs: _____

Corrective Action: _____ Date: _____

Comment: Contractor Indicated that exploratory Pipe line bore holes at juncture of Access Road entrance with Local Rd would be covered to prevent Endangerment of Wildlife by end of Day. Refer to Photos attached.

Corrective Action: _____ Date: _____

On Site Inspection (305):Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities				
Facility ID: <u>449386</u>	Type: <u>WELL</u>	API Number: <u>045-23434</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449387</u>	Type: <u>WELL</u>	API Number: <u>045-23435</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449388</u>	Type: <u>WELL</u>	API Number: <u>045-23436</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449389</u>	Type: <u>WELL</u>	API Number: <u>045-23437</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449390</u>	Type: <u>WELL</u>	API Number: <u>045-23438</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449391</u>	Type: <u>WELL</u>	API Number: <u>045-23439</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449392</u>	Type: <u>WELL</u>	API Number: <u>045-23440</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449393</u>	Type: <u>WELL</u>	API Number: <u>045-23441</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449394</u>	Type: <u>WELL</u>	API Number: <u>045-23442</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449395</u>	Type: <u>WELL</u>	API Number: <u>045-23443</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449396</u>	Type: <u>WELL</u>	API Number: <u>045-23444</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449397</u>	Type: <u>WELL</u>	API Number: <u>045-23445</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449398</u>	Type: <u>WELL</u>	API Number: <u>045-23446</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449399</u>	Type: <u>WELL</u>	API Number: <u>045-23447</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449400</u>	Type: <u>WELL</u>	API Number: <u>045-23448</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449401</u>	Type: <u>WELL</u>	API Number: <u>045-23449</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449402</u>	Type: <u>WELL</u>	API Number: <u>045-23450</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449403</u>	Type: <u>WELL</u>	API Number: <u>045-23451</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>
Facility ID: <u>449404</u>	Type: <u>WELL</u>	API Number: <u>045-23452</u>	Status: <u>XX</u>	Insp. Status: <u>CI</u>

Inspector Name: Colby, Lou

Facility ID: 449405	Type: WELL	API Number: 045-23453	Status: XX	Insp. Status: CI
Facility ID: 449406	Type: WELL	API Number: 045-23454	Status: XX	Insp. Status: CI
Facility ID: 449407	Type: WELL	API Number: 045-23455	Status: XX	Insp. Status: CI
Facility ID: 449408	Type: WELL	API Number: 045-23456	Status: XX	Insp. Status: CI
Facility ID: 449409	Type: WELL	API Number: 045-23457	Status: XX	Insp. Status: CI

COGCC Comments

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS. Refer to Photos attached for more detail	colbyl	03/21/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680101592	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4106214