

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/21/2017

Submitted Date:

03/23/2017

Document Number:

672500477**FIELD INSPECTION FORM**

Loc ID 305447 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 370 17TH STREET #2170City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
		Cogcc.inspections@crestonepr.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434333	WELL	DG	10/17/2016	LO	123-38104	Woolley Sosa 2A-7H-E168	DG
434334	WELL	DG	11/03/2016	LO	123-38105	Woolley Becky 2F-7H-E168	DG
434335	WELL	DG	10/23/2016	LO	123-38106	Woolley Sosa 2D-7H-E168	DG
434336	WELL	DG	11/01/2016	LO	123-38107	Woolley Becky 2D-7H-E168	DG
434337	WELL	DG	10/18/2016	LO	123-38108	Woolley Sosa 2B-7H-E168	DG
434338	WELL	DG	10/30/2016	LO	123-38109	Woolley Becky 2B-7H-E168	DG
434339	WELL	DG	10/24/2016	LO	123-38110	Woolley Sosa 2E-7H-E168	DG
434340	WELL	DG	10/29/2016	LO	123-38111	Woolley Becky 2A-7H-E168	DG
434341	WELL	DG	11/02/2016	LO	123-38112	Woolley Becky 2E-7H-E168	DG
434342	WELL	DG	10/26/2016	LO	123-38113	Woolley Sosa 2F-7H-E168	DG
434343	WELL	DG	11/05/2016	LO	123-38114	Woolley Becky 2H-7H-E168	DG
436731	WELL	DG	10/31/2016	LO	123-39241	Woolley Becky 2C-7H-E168	DG
436733	WELL	DG	11/04/2016	LO	123-39242	Woolley Becky 2G-7H-E168	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 0		corrective date
Comment:	APPROX 32' SOUND WALLS AROUND LOCATION		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Field Flare	
Comment:	NOT IN USE AT TIME OF INSPECTION	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 434333	Type: WELL	API Number: 123-38104	Status: DG	Insp. Status: DG
Facility ID: 434334	Type: WELL	API Number: 123-38105	Status: DG	Insp. Status: DG
Facility ID: 434335	Type: WELL	API Number: 123-38106	Status: DG	Insp. Status: DG
Facility ID: 434336	Type: WELL	API Number: 123-38107	Status: DG	Insp. Status: DG
Facility ID: 434337	Type: WELL	API Number: 123-38108	Status: DG	Insp. Status: DG
Facility ID: 434338	Type: WELL	API Number: 123-38109	Status: DG	Insp. Status: DG
Facility ID: 434339	Type: WELL	API Number: 123-38110	Status: DG	Insp. Status: DG

Complaint

Comment:

Complaint #: 200441210

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 3-17-2017 Time 0800 Hrs

Contacted by Inspector:

Date: 3-17-2017 Time 1600 Hrs

Well Number#: Location #: 305447

Inspection Document #: 672500477

Complainant: Charles Brans Phone: 720-318-4416

Address: 103 Baker Ln Erie CO 80516

Nature of complaint: Noise

Field Inspector Actions:

On 3-17-2017, I was contacted by James Precup NE supervisor of the COGCC in reference to a noise complaint at the residence of the complainant Charles Brans 103 Baker st Erie.

I performed a complete site inspection of the location on 3-17-2017. At the time of inspection, I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints. I also reviewed Environmental Noise Control Inc. continuous sound study information.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Ensign Pusher/Rig Manager: Robert
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES
 Pressure Test BOP: Pass Test Pressure PSI: _____ Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: YES Unlined Pit: YES Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: YES Disposal Location: Waste connection

Comment: Lights pointed toward the ground and center of location

Corrective Action: _____ Date: _____

Facility ID: 434340 Type: WELL API Number: 123-38111 Status: DG Insp. Status: DG

Facility ID: 434341 Type: WELL API Number: 123-38112 Status: DG Insp. Status: DG

Facility ID: 434342 Type: WELL API Number: 123-38113 Status: DG Insp. Status: DG

Facility ID: 434343 Type: WELL API Number: 123-38114 Status: DG Insp. Status: DG

Facility ID: 436731 Type: WELL API Number: 123-39241 Status: DG Insp. Status: DG

Facility ID: 436733 Type: WELL API Number: 123-39242 Status: DG Insp. Status: DG

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): YES

Comment: NOT IN USE AT TIME OF INSPECTION

Pilot: ON

Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Vehicle Tracking		
Rip Rap	Pass					
Ditches	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT