

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2017

Submitted Date:

03/23/2017

Document Number:

674703765

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335235 _____ LONGWORTH, MIKE _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2716	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211229	WELL	PR	02/10/1997	GW	045-06988	FEDERAL GM 13-35	PR
211230	WELL	PR	09/11/2000	GW	045-06989	FEDERAL DOE 2-M-35	PR
439746	WELL	XX	10/26/2016	LO	045-22578	Federal GM 11-35	ND
439747	WELL	XX	10/26/2016	LO	045-22579	Federal GM 21-35	ND
439748	WELL	XX	10/26/2016	LO	045-22580	Federal GM 323-35	ND
439753	WELL	XX	10/26/2016	LO	045-22581	Federal GM 423-35	ND
439763	WELL	XX	10/26/2016	LO	045-22582	Federal GM 44-34	ND
439771	WELL	XX	10/26/2016	LO	045-22584	Federal GM 513-35	ND
439776	WELL	XX	10/26/2016	LO	045-22585	Federal GM 421-35	ND
439779	WELL	XX	10/26/2016	LO	045-22586	Federal GM 444-34	ND
439786	WELL	XX	10/26/2016	LO	045-22588	Federal GM 321-35	ND
439788	WELL	XX	10/26/2016	LO	045-22589	Federal GM 322-35	ND
439789	WELL	XX	10/26/2016	LO	045-22590	Federal GM 313-35	ND
439790	WELL	XX	10/26/2016	LO	045-22591	Federal GM 312-35	ND

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective ActionL			Date:

Overall Good:

Emergency Contact Number:			
Comment:	970-285-9377		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	<u>211229</u>	Type:	<u>WELL</u>	API Number:	<u>045-06988</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>211230</u>	Type:	<u>WELL</u>	API Number:	<u>045-06989</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Producing well</u>							Date:	
Corrective Action:								Date:	
Facility ID:	<u>439746</u>	Type:	<u>WELL</u>	API Number:	<u>045-22578</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439747</u>	Type:	<u>WELL</u>	API Number:	<u>045-22579</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439748</u>	Type:	<u>WELL</u>	API Number:	<u>045-22580</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439753</u>	Type:	<u>WELL</u>	API Number:	<u>045-22581</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439763</u>	Type:	<u>WELL</u>	API Number:	<u>045-22582</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439771</u>	Type:	<u>WELL</u>	API Number:	<u>045-22584</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439776</u>	Type:	<u>WELL</u>	API Number:	<u>045-22585</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439779</u>	Type:	<u>WELL</u>	API Number:	<u>045-22586</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439786</u>	Type:	<u>WELL</u>	API Number:	<u>045-22588</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439788</u>	Type:	<u>WELL</u>	API Number:	<u>045-22589</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439789</u>	Type:	<u>WELL</u>	API Number:	<u>045-22590</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>
Facility ID:	<u>439790</u>	Type:	<u>WELL</u>	API Number:	<u>045-22591</u>	Status:	<u>XX</u>	Insp. Status:	<u>ND</u>

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Gravel	Pass					
Berms	Pass					
Seeding	Fail					
		Compaction	Pass			
Check Dams	Pass					
		Culverts	Pass			
Compaction	Pass					
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT