

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2017

Submitted Date:

03/24/2017

Document Number:

679902395**FIELD INSPECTION FORM**
 Loc ID 338174 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 86610Name of Operator: CAERUS WASHCO LLCAddress: 1001 17TH STREET - STE #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|------------------------------|---------|
| Sprague, Chuck | 970-630-0214 | csprague@caerusoilandgas.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 293462 | WELL | PR | 08/01/2008 | GW | 125-11053 | SCHAFER 22-25 | PR |

General Comment:

Location

| | | | |
|--------------------|-----------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through pasture | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|------------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by unit | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Lease signs mounted on meter sheds | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Metal panels around VGS and meter sheds | | |
| Corrective Action: | | Date: | |
| Type | PUMP JACK | | |
| Comment: | Metal panels around unit and wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Separator | # 3 | | |
| Comment: | 3-Vertical gas separators 50% buried by meter sheds | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Electric motor | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 2 | | |
| Comment: | Electric panel and telemetry equipment at meter sheds | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------|---|-------|--|
| Type: Pump Jack | # 1 | | |
| Comment: | Sentry unit | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 3 | | |
| Comment: | Shared meter run for (SCHAFER 11-25, 13-25, 22-25) 600' WSW | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 293462 | Type: | WELL | API Number: | 125-11053 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production. Central meter run for (SCHAFER 11-25, 13-25, 22-25) 600' WSW @ 39.76766/-102.25179 | | | | | | | | |
| Corrective Action: | | | | | | | | Date: | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gradient Terraces | Pass | | | |
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT