

Inspection Photos
Location Name: Bruton 30-10 Pad
Facility ID: 418985



Photo 1. Damaged fence around wellheads. Taken 3/1/17



Photo 2. Damaged fence taken at follow up inspection.