

Inspection Photos
Location Name: Ptasynski 4
API: 05-081-06353



Photo 1. View at entrance to location facing north.

Inspection Photos
Location Name: Ptasynski 4
API: 05-081-06353



Photo 2. View of pit standing at southeast corner looking northwest.



Photo 3. View of pit standing at southeast corner looking northeast during 6/15/2016 inspection.

Inspection Photos
Location Name: Ptasynski 4
API: 05-081-06353



Photo 4. No tank label.



Photo 5. No tank label from 6/15/2016 inspection.