

Inspection Photos
Location Name: Ptasynski 3
API: 05-081-06354



Photo 1. View of location from entrance facing west.



Photo 2. Wooden boxes on perimeter of location.

Inspection Photos
Location Name: Ptasynski 3
API: 05-081-06354



Photo 3. Separator parts on ground near separator.



Photo 4. Pit behind separator.