

Inspection Photos
Location Name: McCallum Unit 189
API: 05-057-064449



Photo 1. View at entrance to location facing northeast.

Inspection Photos
Location Name: McCallum Unit 189
API: 05-057-06449



Photo 2. Stained soil at wellhead.



Photo 3. Close-up of leak at wellhead.