

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/20/2017

Submitted Date:

03/20/2017

Document Number:

675204040**FIELD INSPECTION FORM**Loc ID 334376 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
McKee, Michael		MMckee@caerusoilandgas.com	EHS
Elsener, Garrett		garrett@caerusoilandgas.com	
Janicek, Jake		JJanicek@caerusoilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295845	WELL	PR	05/06/2010	GW	045-15821	PARACHUTE RANCH FEDERAL 35-32D	PR
295854	WELL	PR	02/28/2010	GW	045-15829	MCNEIL FEDERAL 35-33D	PR
295855	WELL	PR	02/26/2010	GW	045-15830	PARACHUTE RANCH FEDERAL 35-43D	PR
295856	WELL	PR	02/13/2010	GW	045-15831	PARACHUTE RANCH FEDERAL 35-33C	PR
295857	WELL	PR	02/11/2010	GW	045-15832	PARACHUTE RANCH FEDERAL 35-33B	PR
295859	WELL	PR	05/09/2010	GW	045-15833	PARACHUTE RANCH FEDERAL 35-42C	PR
295860	WELL	PR	05/04/2010	GW	045-15834	PARACHUTE RANCH FEDERAL 35-33A	PR
295861	WELL	PR	03/16/2010	GW	045-15835	PARACHUTE RANCH FEDERAL 35-43C	PR
295862	WELL	PR	09/01/2014	GW	045-15836	PARACHUTE RANCH FEDERAL 35-43A	PR
295863	WELL	PR	03/16/2010	GW	045-15837	PARACHUTE RANCH FEDERAL 35-43B	PR
295865	WELL	PR	04/23/2010	GW	045-15838	PARACHUTE RANCH FEDERAL 35-42D	PR

**General Comment:**

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>295845</u>	Type:	<u>WELL</u>	API Number:	<u>045-15821</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295854</u>	Type:	<u>WELL</u>	API Number:	<u>045-15829</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295855</u>	Type:	<u>WELL</u>	API Number:	<u>045-15830</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295856</u>	Type:	<u>WELL</u>	API Number:	<u>045-15831</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295857</u>	Type:	<u>WELL</u>	API Number:	<u>045-15832</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295859</u>	Type:	<u>WELL</u>	API Number:	<u>045-15833</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295860</u>	Type:	<u>WELL</u>	API Number:	<u>045-15834</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295861</u>	Type:	<u>WELL</u>	API Number:	<u>045-15835</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295862</u>	Type:	<u>WELL</u>	API Number:	<u>045-15836</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295863</u>	Type:	<u>WELL</u>	API Number:	<u>045-15837</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Facility ID:	<u>295865</u>	Type:	<u>WELL</u>	API Number:	<u>045-15838</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			
Gravel	Pass					
Berms	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401237991	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4103068">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4103068</a>