



Photo 1: View of the project area from the southern corner facing center.



Photo 2: View of the southeastern portion of the project area from the southern corner facing northeastward. Revegetation is largely comprised of grasses such as crested wheatgrass (*Agropyron cristatum*) and Intermediate wheatgrass (*Thinopyron intermedium*), and orchardgrass (*Dactylis glomerata*).



Photo 3: View of the northeastern portion of the project area from the eastern corner facing northwestward.



Photo 4: View of the southwestern portion of the project area from the southern corner facing northwestward.



Photo 5: View of netting debris within the interim reclamation area. Additional pieces of netting and liner debris are scattered around the interim reclamation areas and should be cleaned up.



Photo 6: View of liner debris within the interim reclamation area.