



Photo 1: View of the project area from the northwestern corner facing center.



Photo 2: View of the western portion of the project area from the northwestern corner facing southward. Revegetation is largely comprised of grasses such as crested wheatgrass (*Agropyron cristatum*) and Intermediate wheatgrass (*Thinopyron intermedium*), and shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*)



Photo 3: View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4: View of rilling occurring within the eastern portion of the project area.



Photo 5: View of perimeter wattles that are full of sediment in the southeastern portion of the project area.



Photo 6: View of erosional channel forming within the southeastern portion of the project area.