

Construction and Stormwater Inspection

March 27, 2017

Operator: BURLINGTON RESOURCES OIL & GAS LP
#26580

Location ID: 442484

Arapahoe County, CO

SESE Section 18 T4S R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Montezuma 4-64 18-13 #4H
Location ID: 442484



Photo 1. Photo taken from the entrance of location, facing East. Culvert installed for planned diversion ditch.



Photo 2. Photo taken from the entrance of location, facing North. Topsoil stockpile stored along the eastern perimeter of the location.

Inspection Photos
Location Name: Montezuma 4-64 18-13 #4H
Location ID: 442484



Photo 3. Photo taken from the northeast location, facing West. No stormwater BMPs have been installed.



Photo 4. Photo taken from the northwest location, facing East. No stormwater BMPs have been installed.

Inspection Photos
Location Name: Montezuma 4-64 18-13 #4H
Location ID: 442484



Photo 5. Photo taken from the western location, facing South. No stormwater BMPs have been installed.



Photo 6. Photo taken from the southwest location, facing East. No stormwater BMPs have been installed.