

Inspection Photos

03/20/2017

Operator: Klabzuba O&G #10148

Location ID: 393690

Inspection Doc. Number: 682501783

Morgan County, CO

SWNE Section 12 T1N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Inspection Photos



Photo 1: Photo of GPS verifying location.

Inspection Photos



Photo 2: Photo taken from the location. Photo shows remnant Musk thistle stalks from 2016 growing season. Musk thistle is a Colorado State listed Noxious Weed and needs to be managed. Photo also shows vegetation in the disturbance area predominantly undesirable weedy cheat grass.



Photo 3: Photo taken from the location. Photo shows remnant Musk thistle stalks from 2016 growing season. Musk thistle is a Colorado State listed Noxious Weed and needs to be managed. Photo also shows vegetation in the disturbance area predominantly undesirable weedy cheat grass.

Inspection Photos



Photo 4: Photo taken from the north end of the location, facing south. Photo shows vegetation in the disturbance area has not achieved uniform desirable perennial vegetative cover. Location is vegetated predominantly undesirable weedy cheat grass.



Photo 5: Photo taken from the south end of the location, facing north. Photo shows vegetation in the disturbance area has not achieved uniform desirable perennial vegetative cover. Location is vegetated predominantly undesirable weedy cheat grass.

Inspection Photos



Photo 6: Photo of vegetation in the reference area. Vegetation seen here predominantly a mix of sideoats grama, western wheat, switch grass and little bluestem.