

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2017

Submitted Date:

03/28/2017

Document Number:

666803057**FIELD INSPECTION FORM**Loc ID 323894 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|-------|------------------------------------|-----------------------------------|
| , Inspections | | COGCCInspectionReports@terraep.com | Field Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 211113 | WELL | PR | 03/29/2010 | GW | 045-06872 | BARRETT RMV 20-35 | PR |
| 439666 | WELL | XX | 10/17/2016 | LO | 045-22552 | Huggard RWF 34-35 | ND |
| 439667 | WELL | XX | 10/17/2016 | LO | 045-22553 | Huggard RWF 334-35 | ND |
| 439668 | WELL | XX | 10/17/2016 | LO | 045-22554 | Huggard RWF 443-35 | ND |
| 439669 | WELL | XX | 10/17/2016 | LO | 045-22555 | Huggard RWF 43-35 | ND |
| 439670 | WELL | XX | 10/17/2016 | LO | 045-22556 | Huggard RWF 44-35 | ND |
| 439671 | WELL | XX | 10/17/2016 | LO | 045-22557 | Huggard RWF 343-35 | ND |
| 439672 | WELL | XX | 10/17/2016 | LO | 045-22558 | Huggard RWF 33-35 | ND |
| 439673 | WELL | XX | 10/17/2016 | LO | 045-22559 | Huggard RMV 70-35 | ND |
| 439674 | WELL | XX | 10/17/2016 | LO | 045-22560 | Huggard RWF 333-35 | ND |
| 439675 | WELL | XX | 10/17/2016 | LO | 045-22561 | Huggard RWF 433-35 | ND |
| 439676 | WELL | XX | 10/17/2016 | LO | 045-22562 | Huggard RWF 344-35 | ND |
| 439677 | WELL | XX | 10/17/2016 | LO | 045-22563 | Huggard RMV 117-35 | ND |

General Comment:[Wells with XX status, Drilling permits expire 12/29/2018](#)

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Plunger Lift

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: [Chemical unit at separator](#)

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|-----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | <100 BBLS | STEEL AST | | 39.479121,-107.853908 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | |
|----------|----|
| Yes/No | NO |
| Comment: | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | | |
|----------------------|--------------|-----------------------|------------|------------------|
| Facility ID: 211113 | Type: WELL | API Number: 045-06872 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Plunger lift | | | |
| Corrective Action: | | | | Date: |
| Facility ID: 439666 | Type: WELL | API Number: 045-22552 | Status: XX | Insp. Status: ND |
| Facility ID: 439667 | Type: WELL | API Number: 045-22553 | Status: XX | Insp. Status: ND |
| Facility ID: 439668 | Type: WELL | API Number: 045-22554 | Status: XX | Insp. Status: ND |
| Facility ID: 439669 | Type: WELL | API Number: 045-22555 | Status: XX | Insp. Status: ND |
| Facility ID: 439670 | Type: WELL | API Number: 045-22556 | Status: XX | Insp. Status: ND |
| Facility ID: 439671 | Type: WELL | API Number: 045-22557 | Status: XX | Insp. Status: ND |
| Facility ID: 439672 | Type: WELL | API Number: 045-22558 | Status: XX | Insp. Status: ND |
| Facility ID: 439673 | Type: WELL | API Number: 045-22559 | Status: XX | Insp. Status: ND |
| Facility ID: 439674 | Type: WELL | API Number: 045-22560 | Status: XX | Insp. Status: ND |
| Facility ID: 439675 | Type: WELL | API Number: 045-22561 | Status: XX | Insp. Status: ND |
| Facility ID: 439676 | Type: WELL | API Number: 045-22562 | Status: XX | Insp. Status: ND |
| Facility ID: 439677 | Type: WELL | API Number: 045-22563 | Status: XX | Insp. Status: ND |

| Environmental | |
|-----------------------------------|--|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): NO | |
| Comment: | |
| Pilot: | Wildlife Protection Devices (fired vessels): YES |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Gravel | Pass | | | |
| | | Ditches | Pass | | | |
| | | Culverts | Pass | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT