

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/22/2017

Submitted Date:

03/28/2017

Document Number:

680000899**FIELD INSPECTION FORM**
 Loc ID 303800 Inspector Name: QUINT, CRAIG On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 82470Name of Operator: STELBAR OIL CORP INCAddress: 1625 N WATERFRONT PKWY #200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Mendenhall, Roscoe	(316) 264-8378	roscoe@stelbar.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253617	WELL	PR	03/05/2007	GW	125-07495	MONK 1-18	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Trail through farm ground		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by well		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease signs by meter sheds		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by tank		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel panels around wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 6		
Comment:	4-VGS's are 50% buried, 2-VGS's are in metal sheds.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:	Central battery f/(Monk 1-18, 2-18, 3-18, 4-18) 690' SW @ 40.30814, -102.56055		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV FIBERGLASS		40.308140,-102.560550

Comment:	24bbl Fiberglass water tank 50% buried	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV PLASTIC		40.308270,-102.560690

Comment:	24bbl Plastic water tank 50% buried	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Location Construction

Location ID: 253617 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: No issues observed

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: _____

Corrective Action: _____

Date: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	253617	Type:	WELL	API Number:	125-07495	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing, Free flow production								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

- 1003b. Area no longer in use? _____ Production areas stabilized ? _____
- 1003c. Compacted areas have been cross ripped? _____
- 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
- Cuttings management: _____
- 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
- Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment:

Access and unused areas of the location are farmed over.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

