

# Inspection Photos

03/24/2017

Operator: Foundation Energy #10112

Location ID: 330865

Inspection Doc. Number: 682501790

Weld County, CO

NWSW Section 21 T5N R61W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Foundation  
Location ID: 330865



**Photo 1:** Photo taken from the well head. Inspection doc. #682501708 documented an audible leak occurring from well. Inspector can no longer detect leak. Sign has been placed at well.



**Photo 2:** Photo taken from the tank battery. Appropriate labeling has been place. Berm along tank battery still remains in improper function condition.

Inspection Photos  
Operator: Foundation  
Location ID: 330865



**Photo 3:** Photo taken from the south end of the location. Photo shows temporary stormwater and sediment control BMPs have not been installed to mitigate stormwater erosion.



**Photo 5:** Photo taken from the north end of the location. Photo shows iron square tubing still stored on the interim area.