

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2017

Submitted Date:

03/22/2017

Document Number:

680401245**FIELD INSPECTION FORM**

Loc ID 335897	Inspector Name: BROWNING, CHUCK	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: <u>100264</u> Name of Operator: <u>XTO ENERGY INC</u> Address: <u>PO BOX 6501</u> City: <u>ENGLEWOOD</u> State: <u>CO</u> Zip: <u>80155</u>				<b>Findings:</b> 16 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Dooling, Jessica	(970) 878-6800	Jessica_Dooling@xtoenergy.com	Piceance Basin Field

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292855	WELL	PR	03/18/2011	GW	103-11090	PICEANCE CREEK UNIT 197-34B3	PR
292858	WELL	PR	08/20/2010	GW	103-11089	PICEANCE CREEK UNIT 197-34B9	PR
292860	WELL	PR	08/11/2010	GW	103-11088	PICEANCE CREEK UNIT 197-34B5	PR
292871	WELL	PR	08/13/2010	GW	103-11087	PICEANCE CREEK UNIT 197-34B4	PR
292873	WELL	PR	08/09/2010	GW	103-11086	PICEANCE CREEK UNIT 197-34B7	PR
292887	WELL	PR	02/09/2011	GW	103-11085	PICEANCE CREEK UNIT 197-34B2	PR
292888	WELL	PR	08/08/2010	GW	103-11084	PICEANCE CREEK UNIT 197-34B1	PR
292889	WELL	PR	08/08/2010	GW	103-11083	PICEANCE CREEK UNIT 197-34B6	PR
292890	WELL	IJ	10/06/2014	DSPW	103-11082	PICEANCE CREEK UNIT 197-34B8	AC
293965	WELL	PR	08/26/2010	GW	103-11146	PICEANCE CREEK UNIT 197-34B10	PR

**General Comment:**

Routine UIC inspection.

**Location****Lease Road:**

Type	Main		
comment:			
Corrective Action		Date:	
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	UIC well inside housing		
Corrective Action:		Date:	

**Equipment:**

Type: Ancillary equipment	#		corrective date
Comment:	Manifold		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	Inside housing		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	292855	Type:	WELL	API Number: 103-11090	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:
Facility ID:	292858	Type:	WELL	API Number: 103-11089	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:
Facility ID:	292860	Type:	WELL	API Number: 103-11088	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:
Facility ID:	292871	Type:	WELL	API Number: 103-11087	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:
Facility ID:	292873	Type:	WELL	API Number: 103-11086	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:
Facility ID:	292887	Type:	WELL	API Number: 103-11085	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:
Facility ID:	292888	Type:	WELL	API Number: 103-11084	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:
Facility ID:	292889	Type:	WELL	API Number: 103-11083	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Flowing					
Corrective Action:						Date:

Facility ID: 292890 Type: WELL API Number: 103-11082 Status: IJ Insp. Status: AC

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**

Inj./Tube: Pressure or inches of Hg 753 Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
(e.g. 30 psig or -30" Hg) Inj Zone: WSTCG

TC: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ Last MIT: 06/17/2016

Brhd: Pressure or inches of Hg 0 Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: Routine UIC inspection. Active injection at time of inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: PUMP FEED

Test Type: \_\_\_\_\_ Tbg psi: \_\_\_\_\_ Csg psi: \_\_\_\_\_ BH psi: \_\_\_\_\_

Insp. Status: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 293965 Type: WELL API Number: 103-11146 Status: PR Insp. Status: PR

**Producing Well**

Comment: Flowing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Ditches	Pass			
Berms	Pass	Gravel	Pass	Self Inspection	Pass	

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401240386	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4105537">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4105537</a>