

Inspection Photos

03/20/2017

Operator: Klabzuba Oil and Gas Inc #10148

Location ID: 393686

Inspection Doc. Number: 682501792

Morgan County, CO

SWNW Section 7 T1N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Klabzuba
Location ID: 393686



Photo 1: Photo of GPS verifying the location.

Inspection Photos
Operator: Klabzuba
Location ID: 393686



Photo 2: Photo taken from the north end of the location, facing southeast. Location appears to have been recently disked, likely per mid contract management requirements for CRP. Note: location seen here is predominantly exposed soil and undesirable grass species such as *Bromus tectorum* (Cheat Grass). Even with the disturbance, this location is not representative to reference areas that have also been disked (see photo 5)



Photo 3: Photo taken from the north end of the location, facing south. Location appears to have been recently disked, likely per mid contract management requirements for CRP. Note: location seen here is predominantly exposed soil and undesirable grass species such as *Bromus tectorum* (Cheat Grass). Even with the disturbance, this location is not representative to reference areas that have also been disked (see photo 5)

Inspection Photos
Operator: Klabzuba
Location ID: 393686



Photo 4: Photo taken from the north end of the location. Location appears to have been recently disked, likely per mid contract management requirements for CRP. Note: location seen here is predominantly exposed soil and undesirable grass species such as *Bromus tectorum* (Cheat Grass). Even with the disturbance, this location is not representative to reference areas that have also been disked (see photo 5)



Photo 5: Photo taken from the adjacent reference area. Photo shows that the reference area has also been disturbed, however exposed soil is minimal and *Bromus tectorum* is at very low densities when compared to the well location.