

Inspection Photos

03/20/2017

Operator: Black Raven Energy Inc #10203

Location ID: 313755

Inspection Doc. Number: 682501805

Morgan County, CO

SWNE Section 6 T1N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Black Raven
Location ID: 313768



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: US Smelting Refining & Mining Co
Location ID: 393763



Photo 2: Photo taken from the south end of the location, facing north. Well has been PA since 2013, however equipment still remains on location.



Photo 3 Photo taken from the west end of the location, facing east. Well has been PA since 2013, however equipment still remains on location.

Inspection Photos
Operator: US Smelting Refining & Mining Co
Location ID: 393763



Photo 4: Photo taken from the east end of the location, facing east. Photo shows equipment, debris and various trash improperly stored on the east end of the location. This will need to be removed.



Photo 5: Photo taken from the east end of the location, facing east. Photo shows equipment, debris and various trash improperly stored on the east end of the location. This will need to be removed.

Inspection Photos
Operator: Black Raven
Location ID: 313768



Photo 6: Photo taken from the east end of the location, facing east. Photo shows equipment, debris and various trash improperly stored on the east end of the location. This will need to be removed.