

Inspection Photos

03/20/2017

Operator: Klabzuba O&G #10148

Location ID: 313751

Inspection Doc. Number: 682501807

Morgan County, CO

SWNW Section 6 T1N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Klabzuba O&G
Location ID: 313751



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Klabzuba O&G
Location ID: 313751



Photo 2: Photo taken from the north end of the location, facing south. Photo shows utility pole remaining on location



Photo 3 Photo taken from the location. Photo shows reclamation area remains sparsely vegetated or exposed soil.

Inspection Photos
Operator: Klabzuba O&G
Location ID: 313751



Photo 4: Photo taken from the adjacent reference area. Photo shows vegetation on the reference area.