



**Photo 1: View of the project area from the northern corner facing center.**



**Photo 2: View of the northeastern portion of the project area from the northern corner facing southeastward. Revegetation is comprised of grazed grasses and rubber rabbitbrush (*Chrysothamnus nauseosus*).**



**Photo 3: View of the northwestern portion of the project area from the northern corner facing southwestward.**



**Photo 4: View of the southwestern portion of the project area from the southern edge facing southwestward.**





**Photo 5: View of erosion occurring within the northeastern portion of the project area (facing downslope).**



**Photo 6: View of more erosion occurring within the northeastern portion of the project area.**