

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/28/2017

Submitted Date:

03/29/2017

Document Number:

666803062**FIELD INSPECTION FORM**

Loc ID 335494 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:12 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280512	WELL	PR	05/08/2006	GW	045-11265	CLOUGH RMV 97-29	PR
280513	WELL	PR	05/08/2006	GW	045-11266	CLOUGH RWF 442-29	PR
280514	WELL	PR	05/08/2006	GW	045-11267	CLOUGH RWF 432-29	PR
297997	WELL	PR	08/27/2008	GW	045-17015	CLOUGH RWF 332-29	PR
297998	WELL	PR	08/27/2008	GW	045-17016	CLOUGH RWF 532-29	PR
297999	WELL	PR	08/27/2008	GW	045-17017	CLOUGH RWF 333-29	PR
298000	WELL	PR	04/30/2009	GW	045-17018	CLOUGH RWF 342-29	PR
298001	WELL	PR	04/30/2009	GW	045-17019	CLOUGH RMV 158-29	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

1

Comment: Chemical unit at wellhead

Corrective Action:

Date:

Type: Plunger Lift

8

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

8

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER

1

<100 BBLS

STEEL AST

Comment: Centralized battery

Corrective Action:

Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type

Capacity

Permeability (Wall)

Permeability (Base)

Maintenance

Comment:

Corrective Action:

Date:

Contents

#

Capacity

Type

Tank ID

SE GPS

PRODUCED WATER

1

300 BBLS

STEEL AST

Comment: Centralized battery

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		39.498044,-107.911122
Comment:					
Corrective Action:					
					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	280512	Type:	WELL	API Number: 045-11265	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	280513	Type:	WELL	API Number: 045-11266	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	280514	Type:	WELL	API Number: 045-11267	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	297997	Type:	WELL	API Number: 045-17015	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	297998	Type:	WELL	API Number: 045-17016	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	297999	Type:	WELL	API Number: 045-17017	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298000	Type:	WELL	API Number: 045-17018	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:
Facility ID:	298001	Type:	WELL	API Number: 045-17019	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Plunger lift					
Corrective Action:						Date:

--

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Waddles	Pass					
		Ditches	Pass			
Slope Roughening	Pass					
		Gravel	In Process			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT