

# Inspection Photos

03/23/2017

Operator: Monsanto Chemical Co #59555

Location ID: 405002

Inspection Doc. Number: 682501830

Weld County, CO

SESE Section 27 T7N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos  
Operator: Monsanto  
Location ID: 405002



**Photo 1:** Photo of GPS verifying location.

Inspection Photos  
Operator: Monsanto  
Location ID: 405002



**Photo 2:** Photo taken from the location facing east. Photo shows vegetation over the reclamation area.



**Photo 3:** Photo taken from the location facing south east. Photo shows vegetation over the reclamation area.