

Inspection Photos

03/23/2017

Operator: MJ Lebsack #50500

Location ID: 405004

Inspection Doc. Number: 682501832

Weld County, CO

SWSW Section 26 T7N R59W

Aaron Trujillo

Reclamation Specialist

COGCC



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Operator: Lesback
Location ID: 405004



Photo 1: Photo of GPS verifying location.

Inspection Photos
Operator: Lesback
Location ID: 405004



Photo 2: Photo of pump jack concrete pad and pipe remaining on location.